



# United States Department of the Interior

BUREAU OF INDIAN AFFAIRS  
Warm Springs Agency  
1233 Veterans Street  
Warm Springs, OR 97761

## **PRELIMINARY (24-HOUR) REPORT**

**FROM:** John Halliday, Superintendent, Warm Springs Agency

**TO:** Stanley Speaks, BIA, NW Region, Director  
Lyle Carlile, BIA, National Interagency Fire Center, Fire Director

**CC:** Robert A. Brunoe, CTWS Natural Resources Director  
Trey Leonard, CTWS Fire Management Officer

## **THE FOLLOWING INFORMATION IS PRELIMINARY AND SUBJECT TO CHANGE**

**LOCATION:** Approximately 30 miles northwest of Warm Springs, Oregon

**DATE OF OCCURRENCE:** July 18, 2014

**TIME OF OCCURRENCE:** 1400 hours (Pacific Daylight Time)

**ACTIVITY:** Wildland Fire Suppression, Initial Attack

**NUMBER & TYPE OF INJURY:** 1 injury, 1 evaluated by medical personnel and released

**NARRATIVE:** On July 18, 2014 at approximately 1400 Pacific Daylight Time a Type 4 wildland fire engine with two personnel aboard was enroute to the 73 fire on an initial attack response. The engine experienced a rollover accident while enroute to the fire. This is a Warm Springs Tribal Fire model 52 engine.

One occupant of the engine was transported by ambulance and then life flight to the hospital with injuries. The second occupant was taken to the hospital for evaluation and released.

A Critical Incident Stress Management and a Serious Accident Investigation Team have been ordered.

**SUBMITTED BY:** John Halliday, Superintendent, Warm Springs Agency